



Identifier	Configuration/MSP	Serial Rx	Telemetry Output	Sensor Input	Peripherals
USB VCP	<input checked="" type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	Disabled / AUTO	Disabled / AUTO
UART1	<input type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	Disabled / AUTO	VTX (IRC Trans) / AUTO
UART2	<input type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	Disabled / AUTO	Disabled / AUTO
UART3	<input type="checkbox"/> 115200	<input checked="" type="checkbox"/>	Disabled / AUTO	Disabled / AUTO	Disabled / AUTO
UART4	<input type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	GPS / 57600	Disabled / AUTO
UART5	<input type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	Disabled / AUTO	Disabled / AUTO
UART6	<input type="checkbox"/> 115200	<input type="checkbox"/>	Disabled / AUTO	ESC / AUTO	Disabled / AUTO

